

Carpenters Work done for Her Royal Highness
Princess Dowager of Wales in Gardens at New
from Mas to Lady Day 1769

By Geo. Warren

1760

Dec. 31st

To the Lights in Lotick Garden
Six Iron Stops 6 Iron Eyes & Large Hooks } 0.. 11.. 2
4 Dozen of Large Wood Screws. }
2 q^{rs} of Elm Board 2 q^{rs} of oak q. 4 & 3. - - - - - 0.. 1.. 0
2 q^{rs} of Sit Deal for Marking Sticks - - - - - 0.. 0.. 9
2 Men 4 Days Each. - - - - - 1.. 0.. 0

To Casing the Greenhouse Doors & Sashes &c
2 Men 1 Day Each. - - - - - 0.. 5.. 0

To Cleaning the Gutters at Back of Greenhouse
2 Men 1/2 a Day Each. - - - - - 0.. 2.. 6

1769

Jan 9th

6 W of Paint to the Rails in hahad - - - - - 0.. 3.. 0

To Making a Skate to pump in Lotick Garden
& Mend of the fences round Trees &c
15 q^{rs} of Sit Deal 1/2 C of C. W. - - - - - 0.. 1.. 6

1 C of 20. 1 C of 10. W. 2 Men 2 Days Each - - - - - 0.. 12.. 0

To the Posts & Rails in hahad
24 q^{rs} of fir q. 6 & 4 - - - - - 0.. 0.. 0

14 q^{rs} of Ditto 6 & 3 - - - - - 0.. 3.. 6

14 q^{rs} of Double Deal 6 in wide - - - - - 0.. 2.. 4

16 q^{rs} of whole Deal - - - - - 0.. 4.. 0

1/2 C of 20. 1 C of 10. W. 7 W of Spikes - - - - - 0.. 6.. 2

2 Men 6 Days Each. - - - - - 1.. 10.. 0

Jan 14th

To the Posts & Rails in Aha &c
20 q^{rs} of inch 12 Deal 20 q^{rs} of fir q. 4 & 3 - - - - - 0.. 9.. 2

10 q^{rs} of 2 1/2 Deal 12 q^{rs} of whole Deal - - - - - 0.. 6.. 4

1 C of 20. W. 7 W of Spikes - - - - - 0.. 4.. 10

2 Men 5 Days Each. - - - - - 1.. 5.. 0

To Mend of the Rails on the Quin Arch &c
12 Spikes 1/2 C of 20. W. 2 Men 1 Day Each - - - - - 0.. 6.. 0

To Mend of the Rails West Mr. Howletts &
Pitching Troughs for Allen fastening posts
& Repairing Gates & other jobs. - - - - -

Car. over - - - - - 0.. 2.. 11

		Bro. over	0.. 2.. 11
	12/5 f. oak Sails 1/2 C of 10. W.		0.. 4.. 0
of 21.	14 W of Sills & Men 1/2 Day Each.		0.. 10.. 0
	To Making a Packing Box for M. Riton		
	16 f. of Split Deal 1 C of 6. W. 1 Days Work		0.. 4.. 4
	To Repairing Doors & Gates in Kitchen Garden & a Gate by Pagoda. &c		
	12 f. of whole Deal		0.. 3.. 0
	1/2 C of 20. 1 C of 10. W. 12 Wood Screws		0.. 1.. 10
	2 Men 1/2 Days Work Each.		0.. 7.. 6
	To the Posts & Rails in Akaha &c		
	36 f. of whole Deal 5 in Wide.		0.. 3.. 9
	6 f. of oak of 6 #4		0.. 3.. 0
	24 f. of fir of 4 #3 of 3 #2 1/2		0.. 1.. 10
	1/2 C of 20. W. 12 Spikes		0.. 3.. 0
of 20.	2 Men 5 Days Each.		1.. 5.. 0
	To putt on Joins to Rails in Akaha		
	2 Men 2 Days Each.		0.. 10.. 0
	To Easing Doors putt on Latches & Easing Light in Lotick Garden 2 Days Work.		0.. 5.. 0
	To Easing Doors & Lights & putt up Shelves in Kitchen Garden 2 Men 1/2 Day Each		0.. 7.. 6
	To Repairing the Lathing Easing Doors & other Jobs at Aviary &c		
	1/2 Dozen of Pantile Laths.		0.. 3.. 0
	12 f. of whole Deal.		0.. 3.. 0
	1 C of 20. 1/2 C of 10. 1 C of 6. W. 16 Spikes		0.. 4.. 2
	1/10 of feather Edge Watten.		0.. 1.. 0
	2 Men 2 Days Each		0.. 10.. 0
Feb 4	To Making & putt on Buttons to Sills in Lotick Garden & other Jobs		
	6 f. of Elm Board. 36 Large Wood Screws		0.. 4.. 6
	2 Men 1 Day Each		0.. 5.. 0
	A New Stocks Lock for Allen.		0.. 2.. 6
	To Mend Doors at Manazery putt up Patches Mend the Lathing Easing Gates &c		
	12 f. of whole Deal 12 f. of Split Deal		0.. 4.. 0
	1 Dozen of Pantile Laths		0.. 2.. 0
	1 C of 20. 1/2 C of 10. W. 1/2 C of Clay W.		0.. 2.. 7
	3 Days Work.		0.. 7.. 6
	Car. on		15.. 4.. 11

		Bro. over	15.. 4.. 11
2.. 11		To Mend the Gate by the River Bank & putt up	
4.. 0		Rails over Ditt ^o 160 ft of Split Deal	0.. 14.. 0
10.. 0		1/2 C of 20. W. 20 Spikes 2 1/2 Days Works	0.. 0.. 7
4.. 4	7.11.	To Easing Doors & Lights & other Jobs in	
		Kitchen Garden 1/2 C of 20. W. 2 Men 1 Day Each	0.. 5.. 0
		To putt on Irons to Rails in Aha and	
3.. 0		Repairing Ditt ^o . 12 ft of whole Deal	0.. 3.. 0
1.. 10		1 C of 20. W. 12 Spikes 2 Men 1 Day Each	0.. 7.. 4
7.. 6		To Making a packing Box for Mr. Aiton	
		12 ft of Split Deal 1/2 C of 6. W. 1/2 a Days Works	0.. 2.. 6
3.. 9		To Easing Lights & Doors 1 Day	0.. 2.. 6
3.. 0		To Repairing the planking at Managery &	
4.. 10		the Lathing &c 1 Dozen of pantile Laths	0.. 2.. 0
3.. 0		1/2 C of 20. 1/2 C of 10. W. 1 C of Boat W. 10 Spikes	0.. 3.. 6
5.. 0		2 Men 1 Day Each	0.. 5.. 0
10.. 0		To paint the Lights in Kitchen Garden &	
		Repairing frames Lights & Doors &c	
5.. 0		100 ft of Elm Board	0.. 4.. 6
		1 C of 20. 1 C of 10. W. 3 lb of Paint.	0.. 3.. 6
7.. 6		3 Days Works	0.. 7.. 6
	7.10.	To Making a Packing Box for Mr. Aiton	
3.. 0		1/10 ft of Leaf of Split Deal 1/4 C of 6. W. 1/4 of a Day	0.. 1.. 9
3.. 0		To Easing Lights &c 1 Day	0.. 2.. 6
4.. 2		To paint Lights in Kitchen Garden & Mend	
1.. 0		the planking in Beach houses &c	
10.. 0		8 ft of Elm Board	0.. 2.. 0
		6 lb of White Lead 2 quarts of Oyle	0.. 6.. 0
4.. 6		12 Spikes 1 C of 20. W. 1 C of 10. D.	0.. 3.. 0
5.. 0		2 Men 3 Days Each	0.. 15.. 0
2.. 6		To the post & Rails in Aha.	
		48 ft of 5/4 g. 5 & 3/2	0.. 9.. 10 1/2
	7.25.	20 Spikes 1 C of 20. W. 2 Men 1 Day Each	1.. 3.. 0
4.. 0		To Altering Drawers &c for Mr. Aiton	
2.. 0		16 ft of 3/4 Deal 1 Days Works	0.. 4.. 6
2.. 7		To putt on Irons to Rails in Aha & Paint	
7.. 6		4 lb of Paint 2 Days Each 2 Men	0.. 12.. 0
4.. 11		Car over	22.. 14.. 1 1/2

	Dec. over	22.. 14.. 1/4
	To Mend 7 Doors & Casings Lights & putt up Shelves in Kitchen Garden &c	
	1/2 C of 20. W. 2 C of 10. W. 1 C of 6. W. 12 Large Screws	0.. 5.. 10
	2 Men 2 Days Each.	0.. 10.. 0
	To Making 12 New Water Troughs for Theacants	
	4/12 of whole Deals 6 C of Back W. 1 C of 10. W. 2	0.. 17.. 4
	2 Days Work.	
Mar. 4.	To altering a Bookcase & Drawers for W. Aiton	
	12 of 1/2" of Mill Deal 1 C of 6. W. 5 C of Boards.	0.. 4.. 6
	a pair of Large Dove-tail hinges & W.	0.. 1.. 0
	To D. & Paint the Lights	
	4 lb of Paint 2 quarts of Oil 2 Men 2 Days Ea	0.. 15.. 0
	To Mend 9 frames Casings Lights & paint L.	
	in Kitchen Garden &c	
	16 of 1/2" of Elm Board 12 of 1/2" of whole Deal	0.. 7.. 0
	1/2 C of 20. 1 C of 10. W. 2 C of Board W.	0.. 4.. 0
	3 Days Work	0.. 7.. 6
	To Casings the Lashes at the Greenhouse	
	putt up Perches & Mend the Lathing for Allen	
	1 Dozen of Pantile Laths 10 of 1/2" of Deal 1 1/2 of 1/2"	0.. 3.. 6
	1/2 C of 20. 1/2 C of 10. W. 1/2 C of Board W.	0.. 2.. 6
	2 Men 1/2 Day Each.	0.. 7.. 6
	To finishing & Pitching Water Troughs	
	1/2 C of 20. W. 1 lb of White Lead 12 lb of Pitch	0.. 4.. 2
	1/2 Days Work.	0.. 3.. 9
	To Making flower Sticks for W. Aiton	
	6/6 of 1/2" Long 6/7 of 1/2" Long 6/10 of 1/2" Long	0.. 9.. 6
7/11.	To Cut off pipes for the hothouse getting Spurs Ready for fences in Kitchen Garden	
	Casings Lights & Mend 3 frames &c	
	12 of 1/2" of whole Deal 12 of 1/2" of Elm Board	0.. 6.. 0
	1/2 C of 20. 1 C of 10. W. 50 Spikes	0.. 6.. 10
	4 Days Work.	0.. 10.. 0
	To Paint Lights &c	
	4 lb of Paint 1 of 1/2" of Oil 1 Days Work	0.. 6.. 0
	To putt up Perches for Allen Mend the pails at the Slip & Casings Gates &c	
	Car. on	29.. 6.. 0 1/4

4. 1/4
5. 10
7. 4
8. 6
10. 0
15. 0
17. 0
18. 0
19. 6
23. 6
24. 6
25. 6
28. 2
30. 9
31. 6
36. 0
37. 10
38. 0
39. 0
40. 0

6/10 of mch 1/2 Laths 1 C of 10. W. 1 1/2 Days Works	0.. 5.. 11
To casing the Lashes at the old Greenhouse Casing Doors & Shutts at the Temples 2 Days Works	0.. 5.. 0
To fastening the post & putt on Irons to Rails in Akah & Mend & fences Round Trees &c 10 ft of whole Deal 10 ft of Split Walks 1 C of 20' 1 C of 10. W. 2 Days Works	0.. 6.. 0 0.. 7.. 0
To gittg the Lights to New frames in Kitchen Garden 1 Days Works	0.. 2.. 6
To Mendg the sails & fastening the Posts by Notick Garden 1 C of 10. W. 1 Days Works	0.. 3.. 2
To fastening the Posts & Mendg the sails at Managery 1 C of 10. W. 12 Spikes 1 Day's Works	0.. 4.. 2
To taking off Locks Cleaning & Cyling D & puttg them on again 1 Days Works & oyle	0.. 3.. 0
To paintg off Lights 1 Day	0.. 2.. 6
To Gettg Spurs Ready & Spuring the posts in Kitchen Garden 20 Spikes 1 C of 20' 1 C of 10. W. 3 Days Works	0.. 4.. 4 0.. 7.. 6
To casing Doors &c in Kitchen Garden 12 Dog W. 12 Wood Screws 1 pair of Dometail 1 Days Works	0.. 2.. 6 0.. 2.. 6
To casing Doors at the upper end of Garden & Mendg the Gate by the Reim Buckage 1 C of 6. W. 6 Dog W. 1 Days Works	0.. 3.. 3
To Making 3 Large Strong Packing Boxes to go abroad 244 ft of whole Deal 12 C of 10. W.	2.. 16.. 0 0.. 0.. 0
To D. & helping to pack up 2 Men 3 Days Each	0.. 15.. 0
To Packing on 6 Directions Red Tasse Tax & Labour	0.. 1.. 0
To Spuring the posts & Mendg the Sails in Kitchen Garden &c	

7/10th

7/25th

Car over — 36 6 0 1/4

	50 Spikes 1 C of 20. 1 C of 10. W. <i>Pross. wca</i>	36.. 6.. 0 1/4
NB - 1-4 under	3 Days Works	0.. 6.. 2
	To taking down Shades & other Jobs for Mr. Aiton	0.. 7.. 6
	1 1/2 Days Works	0.. 3.. 9
	To painting Lights & frames &c	
	6 C of Paint 1 Days Works	0.. 5.. 6
	To putt on Irons to Rails in Ash & painting &c	
	3 C of Paint 3 Days Works	0.. 9.. 0
	1 C of 20. W. for Mr. Aiton's use	} 0.. 2.. 0
	1 C of 20. W. for Mr. Padmore use	

£ 30.. 0.. 7 1/4

Ap^o: 27th Exam^d W^m Chambers

Rec^d. May 20th 1769 of Her Royal Highness
Princess Dowager of Wales by the Hands of
W^m Chambers Esq. the Contents in full of
this Bill

£ Geo: Warren

£ 30.. 0.. 7 1/4

td.

0/4
2/6
9
6
0
0
7/4

Handwritten text, possibly a signature or name, written in cursive script.

Warren Farquhar
38¹/₂ O. 7¹/₄