

Carpenters Work Done for Her Royal Highness  
Princess Dowager of Wales in Gardens at New Frome  
Lady Day to Midsummer 1769

1769

G. Geo. Warren

April 1<sup>st</sup>

To fastening on the Ornaments at Manery &  
other jobs, 1 C of Tenter Hooks, 1 C of Cord W. — 0.. 1.. 6  
2 Men 2 Days Each — 0.. 10.. 0

To putt on Lines to Lights in Kitchshouse  
10 lb of Line & 2 Men 1 Day Each — 0.. 13.. 4

To Casing Lights & Mend the planking in  
the Pitts oyling the Bolts at Lighthouse & other jobs  
1 C of 20. W. 2 Dozen of Wood Screws 3 Days Work  
& oyl — 0.. 10.. 4

To taking off Locks cleaning & oyling them & putt  
them on again 1 Days Work & oyl — 0.. 3.. 0

To Making a Lid to a Packing Box for Mr. Piton  
10 f. of Mit Deal 1/2 C of Board W. 1/2 Days Work — 0.. 1.. 0 1/2

20<sup>th</sup>

To Casing & hanging some of Greenhouse Stitches  
& Paint Ditto. 1 C of Line — 0.. 5.. 0  
1/2 C of Cord W. 2 lb of paint 2 Men 1/2 Day Each — 0.. 0.. 9

To Repairing the Boxes in the Pitts in Kitchens  
Garden & paint Water Troughs &c  
1 C of 20. W. 1 C of paint 1/2 Days Work — 0.. 6.. 7

To Mend frames Casing Doors & putt up  
Shelves in Kitchen Garden &c

10 f. of whole Deal 10 f. of Elm Board — 0.. 9.. 0  
1 C of 20. 1 C of 10. 1 C of C. W. — 0.. 2.. 0

a pair of Large Hinges & Screws. — 0.. 3.. 6  
2 Men 2 Days Each — 0.. 10.. 0

To putt up flower Stages & Brackets & paint  
Ditto in Back flower Garden &c

16 f. of Elm Board — 0.. 4.. 0  
1 C of 20. W. 2 Dozen of Wood Screws. — 0.. 2.. 4

3 Days Work — 0.. 7.. 6

To a New Door in Kitchen Garden  
19<sup>th</sup> 1/2 Sup. whole Deal Door plow. & Tongued — 0.. 13.. 0

16 f. of 1/4 Deal 5 m Wide for Linnings plain — 0.. 2.. 6  
Car. over — 5.. 14.. 0 1/2

	Butt over	5. 14. 0 1/2
27/15.	To Repairing a Larder Window at Lotick Lighthouse & other jobs 20 ft. of Birch Deal, 1 C of 10. W. 2 Days Work	0. 4. 2 0. 5. 0
	To Repairing the Small Bridge that goes to Joleland &c 16 ft. of Elm Board. 1/2 C of 20. W. 1 Days Work.	0. 4. 0 0. 3. 2
	To putt up Stages at the back flower garden fastening posts casing Doors & other jobs. 10 ft. of Elm Board 1 C of 20. 1 C of 10. W. 3 Days Work.	0. 4. 6 0. 9. 0
	To taking down Shades getting ready Border boards & Making Packing Boxes for Mr. Alton &c. 40 ft. of 1/2 Deal, 1 C of 10. 1/2 C of 20. 1 C of 6. W. 2 Men 2 Days Each.	0. 0. 0 0. 10. 0
	To Repairing the Lathing at the Aviary &c 1 Dozen of scutler Laths, 1 C of 10. W. 1/2 C of 6. W. 2 Men 1 Day Each.	0. 3. 4 0. 5. 0
27/22.	To hanging & painting a Door in Kitchen Gard. a pair of Large Charnetts & W. 1/2 Days Work & painting &c	0. 4. 0 0. 3. 1/2
	To Mend frames casing Lights in Kitchen Garden &c 12 ft. of Elm Board. 1 C of 20. 1 C of 10. W. 1 Days Work.	0. 3. 0 0. 4. 0
	To Repairing Lights over the Pinehouse 12 lb of Oil Copes 1 C of Boat W. & 3 Candles 2 Men 2 1/2 Days Each.	0. 10. 0 0. 1. 3 0. 12. 6
	To taking down & putt up Shades in Lotick Gard. & painting Border Boards &c 1 C of 26. 1 C of 10. 2 C of 6. W. 1 C of Penter Hooks 3 lb of paint 3 Days Work.	0. 13. 2
	To Mend Cradles & frames in flower garden 1 C of 6. W. 1 C of Boat W. 1 Days Work	0. 4. 0
	To Repairing hanging & casing Lashes at Greenhouses &c 4 lb of Oil Cope 6 ft. of Split Deal. 1/2 C of 20. W. 1 C of Boards 2 Men 1 1/2 Day Each	0. 3. 10 0. 1. 2 0. 7. 6
	Car. on	11. 19. 9

0 1/2	29 <sup>th</sup>	To Repairing part of the Mosque Temple	
2		130 ft of fir of 4 1/2 B.	1. 1. 0
0		24 ft of inch 1/2 Deal & 1/2 of Watters.	0. 11. 6
0		1/12 of feather edged Watten.	0. 1. 0
0		3 C of 20. 3 C of 10. 2 C of 6. W. 30 Spikes.	0. 10. 0
2		2 Men 6 Days Each.	1. 10. 0
6		To the Balona Temple	
0		To putt on Slips for the Plummer.	
0		12 ft of inch Deal 1/2 C of 6. W. 1 Days Work.	0. 4. 9
0		To taking down Shades & putt up border boards	
0		& Making Boxes in Exotick Garden &c	
0		30 ft of Elm board 12 ft of whole Deal.	0. 10. 6
0		1/2 C of 20. 2 1/2 C of 10. 1 C of 6. W.	0. 4. 7
0		2 Men 3 Days Each.	0. 15. 0
4	May 6 <sup>th</sup>	To Mend Cowhouse Doors & gates & rails	
0		12 1/2 ft oak rails 1 C of 20. 1 C of 10. W.	0. 5. 2
0		1 New Stock Locks 1 Days Work.	0. 5. 0
0		To taking down & putt up Shades & Making	
1 1/2		packing Boxes & other Jobs in Exotick Garden	
0		2 1/2 ft Leaves of Sit Deal.	0. 2. 4
0		1 C of 20. 1 C of 10. 1/2 C of 6. W. 3 Days Work	0. 9. 5
0		To Mend Doors & frames & paint in Garden	
0		12 ft of whole Deal 1/12 ft Sit Deal.	0. 4. 2
0		1/2 C of 20. 1 C of 10. W. 1/2 C of Wood W.	0. 3. 0
0		6 lb of paint 2 Men 2 Days Each.	0. 13. 0
0		To Repairing the Engine 1 Day.	0. 2. 6
3		To paint 12 Orange Tubs 3 Times	0. 10. 0
6		To the Mosque Temple To Repairing the	
2		floor & putt up Cornice & Mend the Door	
0		9 1/2 ft whole Deals 2 1/2 ft Watters	1. 2. 6
0		12 ft of fir of 4 1/2 B.	0. 2. 0
0		1 C of flooring boards 2 C of 20. 2 C of 10. W.	0. 5. 4
0		2 Men 6 Days Each.	1. 10. 0
10		To casing Door size at Pagoda.	
2		2 Men 1 Day Each.	0. 5. 0
6	13 <sup>th</sup>	To Making Pheasant Boxes for Allen	
9		84 ft of inch Deal 12 ft of fir of 4 1/2 B.	0. 14. 0
		4 Dozen of Large Wood screws	0. 3. 0
		1/2 C of 20. 1 C of 10. W. 1 C of Boat W.	0. 3. 10
		Car. over	24. 19. 0

2 pair of Large Dooetaild Linges & W. Pro. over — 24. 19. 0  
 4 Days Work 0. 2. 0  
 To Repairing a Door & frames & Easing  
 Lights in Lottick Garden &c 0. 10. 0  
 12 f. # of whole Deals 0. 3. 0  
 1 C of 20. 1/2 C of 10. W. 4 holdfasts 1 f. Long Each 0. 3. 9  
 1/2 Days Work. 0. 3. 9  
 To Flowing the planks at the Back of  
 Green house & Men 1 Day Each. 0. 5. 0  
 To putt on Irons to Rails in Ash & Taking  
 Down the Boards of the Stage in Back flower  
 Garden Mend & Easles & other jobs  
 6 partite Laths, 1 C of 6. 1/2 C of 10. W. 0. 1. 11  
 1 C of Wood W. & Days Work. 0. 6. 0  
 To Making 6 Dozen of Wedges for the Light  
 in Kitchen Garden 0. 12. 0  
 To a New Sky Light at Balona Temple  
 & fixing D. 1. 5. 0  
 To Repairing the Mosque Temple  
 New quartering the West end & part of the front  
 & Repairing the Mouldings &c  
 230 f. of f. of 4 & 4. 2. 7. 11  
 4/12 f. whole Deals & 1/12 f. Wathens. 0. 14. 0  
 3 C of 20. 3 C of 10. 2 C of 6. W. 30 Spikes 0. 10. 0  
 2 Men 5 1/2 Days Each. 1. 7. 6  
 To Making Copes to hold up Net over Pond  
 Boxes Mend & Pushes Easing Doors &c  
 12 f. # of whole Deals, 1 C of 20. 1 C of 10. W. 0. 5. 2  
 2 C of Tenter hooks & Days Work 0. 7. 0  
 To taking the Canvas of the flower Stage  
 & other jobs 1 Days Work 0. 2. 6  
 To taking down part of the Orange Stages  
 at Greenhouse & Moving the planks &c  
 2 Men 4 Days Each 1. 4. 0  
 2 Labourers 1 Day Each 0. 1. 4  
 1 C of 20. W. To Kitchen Garden 0. 1. 4  
 1 C of 20. W. for W. Autons use. 0. 1. 4  
 To the Turkish Mosque  
 3/12 f. Wathens 3 C of 10. W. 2 1/2 C of Beads 9. 3  
 2 Dozen of Wood Screws 36. 2. 1  
 Cap. on

7. 20. #

9

Pur

0		7 Days Work.	0.. 17.. 6
0	of 27.	To taking off Locks in Kitchen Garden	
0		Cleaning & oyling D. & putt'g them on again	
0		1 Dozen of Large Wood Screws 1 Days Wk & oyl.	0.. 3.. 9
0		To putt'g Spurs to Gate posts by Engine &	
9		2 Large oak Spurs & 6 Spikes	0.. 3.. 6
9		To D. & putt'g on Irons to Akha Easing	
0		Lights & Repairing frames in Kitchen Gard.	
0		1 C of 20. W. & 2 Men 2 Days Each.	0.. 11.. 4
0		To taking down the Stages in Greenhouse &	
0		Moving planks & Trussels & placing D. in them	
11		2 Men 1/2 Days Each	1.. 2.. 6
0		1 C of 20. W. for the Painters use.	0.. 1.. 4
0		1 C of 20. W. for Gardeners use.	0.. 1.. 4
0		To the Mosque Temple	0.. 7.. 6
0		36 f. of fir 4 & 4	0.. 2.. 9
0		1 1/2 C of 20. W. 1 1/2 C of Brads	0.. 10.. 0
0		4 Days Work.	0.. 4.. 9
11		To oyling Bolts & hinges at Pagoda & Easing	0.. 10.. 0
0		Doors & 1 1/2 Days work & oyl.	0.. 4.. 9
0		To Paint 12 Orange Subs 3 Times over	0.. 10.. 0
11	June 3.	To Taking down all the Lights at Katick	
0		Hot house Easing them & putt'g them up again	
0		2 C of Soap & Men 4 Days Each	1.. 11.. 0
6		To putt'g up Laths for M. Aiton	
0		36 f. of Deal inch 1/2	0.. 1.. 6
0		6 Large hold fasts 1/2 C of 20. W. 1 Days Work.	0.. 4.. 0
2		To the Green house Stowing the planks and	
0		Mend'g the Lung Repairing fences round Pices	
0		& other jobs 2 Men 2 Days Works Each	0.. 10.. 0
6		To putt'g pails Ready for fence by Pond side	
0		40 oak pails 3 f. Long Each.	0.. 6.. 0
0		3 1/2 f. of Deals 2 Men 1/2 Day Each.	0.. 11.. 6
0		To Mend'g the Back part of Aviary	
4		1 Dozen of pantile Laths 2 1/2 f. inch Deals	0.. 5.. 4
4		2 1/2 f. Leaves of Split Deal.	0.. 2.. 4
0		1 C of 20. 1 C of 10. 1 C of 6. W. 12 Spikes.	0.. 3.. 0
3		2 Men 1/2 Day Each	0.. 7.. 6
1		Car. over	45.. 10.. 6



	1 Dozen of pantile Laths 4/12 of Laths inch 1/4 Sq <sup>o</sup>	55. 14. 3
6	12 of whole Deal	0. 3. 4
0	1/2 C of 20. 1 C of 10. W. 1/2 C of Wood W.	0. 3. 0
6	2 Days Work.	0. 2. 0
	To the Pagoda Repairing the Door frames	0. 5. 0
	Linings & Scirting & Painting Ditto.	
4	2/10 of whole Deals or 7 of 1/2 of 6 & 3.	0. 5. 9
0	1 C of 20. 1 C of 10. 1 C of 6. W.	0. 2. 0
4	4 Days Work & paint.	0. 12. 6
0	To Repairing the Minarets at the Mosque	
6	4/12 of whole Deals 1/12 of Watten	0. 10. 4
	12 of 2 1/2 Deal	0. 4. 0
10	1 1/2 C of 20. 1 C of 10. 1 1/2 C of 6. W.	0. 3. 7
0	1 1/2 C of Heads & 12 Spikes.	0. 1. 9
	4 1/2 Days Work	0. 11. 3

Aug 9<sup>th</sup> 1769 Exam<sup>d</sup> W<sup>m</sup> Chamberlain £ 50. 19. 5

Rec<sup>d</sup> Aug. 19. 1769 of Her Royal Highness  
 Princess Dowager of Wales by the Hands of  
 W<sup>m</sup> Chamberlain Esq. the full Contents of this  
 Bill  
 £ 50. 19. 5  
 J. Geo. Warren

584 1945  
Hansen Carpenters